


65D1119


# KDL-DC/AC SERIES INSTALLING AND USING ILLUMINATION

## 1. THE PICTURE OF STRUCTURE



## 2. INSTALL PROCESS

A. Separate ④ to make both of left and right horse level



B. Put two ⑧ insert ④ one by one

D. According to ⑬ above of ⑭, adjust the both balance height of ⑭. Then locked ⑫

E. Enclose printing fabric (KDL-DC)

F. Readjust ⑬ make ⑫ drive while ① hanging up and locked ⑫

⑫ Drive pipe must be hang up while driving ① in the mainframe crust.

Special Note: don't pull out the connecting line of bottom (KDL-DC).

Drive pipe ② can take out

(KDL-AC) The way of knocked-down ②

The way of knocked-down ⑥ (KDL-DC)

Illuminate:

The picture adopt white printing with coat  
The width of picture are total machine wide minus 65-68mm.  
The max of picture height are 1900mm.